



BUREAU
VERITAS

Industry & Facilities

Certificate N° IDD/Q-06/007-P/O 3261 IC

INSPECTION CERTIFICATE 3.2 FOR Metallic Products
According to EN 10204: 2004

Supplier: Cangzhou Hengli Pipe Fitting Manufacturing Co.,Ltd. Ref. N°: IDD/Q-06/007

Location: East Yanta Road ,Yanshan, Hebei Province

Purchaser: Chemtech Alloys Pvt. Ltd.

Purchase order N°:
CAPL/C-3261/2006-07

Product designation / Description

Pipe Fitting/Flange

Pipe Fitting:

H74583589.H74583563.H74583564.H74583565.H74583552.
H74583513.H74587545.H74588552.H74588553.H74583589.
H74583563.H74583564.H74583565.H74587678.H74587545.

Heat / batch N°

Flange:

051210.

Quantity:

1686 pieces of fittings+752 pieces of flanges

Product specification

Specification or grade & standard:

ASTM A234 GR.WPB, GR.B, B16.9, A105 , B16.5, B36.10

Additional testing/examination specified on the order if any: N/A

Inspection results

Inspection carried out by: Li Jian

Date of inspection: 8th-9th and 12th Jan, 2007

Number of pages enclosed: 6 pages of inspection report and 10 pages of Mill Test Certificate.

Identification of enclosures:

Inspection report No.: IR IDD/Q-06/007-P/O3261, Mill Test Certificate No: 07-001

Markings ensuring the traceability between the product and the documentation: The above mentioned Heat No.

Comments or particular mentions: HB test was replaced by HV test because of lack of HB test equipment, then the HV data was transformed into the HB data, the results were accepted.

The products as described above were checked and inspected, under the supervision of Bureau Veritas within the scope of General Conditions, in accordance with the technical specifications of the purchase order.

Purchaser's authorized representative

Surveyor's Name:

Li Jian

Place/date:

Shanghai

2007/1/15

Signature:

